



RECREATIONAL AVIATION AUSTRALIA INC

5 July 2005

ULTRALIGHT AIRCRAFT AIRWORTHINESS NOTICE
AIRWORTHINESS NOTICE IDENTIFICATION NUMBER : 050705-1

Savannah and Bingo Aircraft

To: All owners and operators of SAVANNAH and BINGO Aircraft.

Background: An in-flight failure of the strut attachment section on the outer wing has led the factory to ground all of its aircraft until further notice. Investigations into the cause of the failure are being conducted at the moment

Discussion: The factory issued the following statement via email to its distributors worldwide:

“Following the accident occurred last week to an airplane model Savanna in Norway, waiting the informations needed to identify the model, the owners and the causes, all the owners of airplane Bingo and Savannah are invited not to make any flight activity until explanation of the causes. ICP will inform all the customers, dealers and authorities as soon as possible.

All ICP dealers must inform all the owners of airplane Savannah and Bingo.”

Further Action: The RA-Aus will broadcast any developments from the factory to the affected owners, until such time as affected serial numbers can be established or until a fix has been approved.

Technical Manager

Defect Reporting is one of the primary ways we have in ensuring continued safety in our operations.